NOKIA Developer

Archived:Certain PIM API operations cause error in Nokia 6270 and Nokia 6230i (Known Issue)

Archived: This article is **archived** because it is not considered relevant for third-party developers creating commercial solutions today. If you think this article is still relevant, let us know by adding the template {{ReviewForRemovalFromArchive|user=~~~~|*write your reason here*}}.

Description

The PIM API implementation in the Nokia 6270 and the Nokia 6230i makes the phone auto-reboot if lots of contacts are added automatically to the Phonebook.

How to reproduce

If you add 100 contacts from the MIDlet to the Contact list, this results in an auto reboot on the Nokia 6270 and the Nokia 6230i.

Solution

Upgrade the software.