NOKIA Developer

Archived:Browser Control sample in S60 3rd MR SDK can't work in emulator (Known Issue)

Archived: This article is **archived** because it is not considered relevant for third-party developers creating commercial solutions today. If you think this article is still relevant, let us know by adding the template {{ReviewForRemovalFromArchive|user=~~~~|*write your reason here*}}.

Overview

The S60 example comes with S60 SDK 3RD Ed. Maintenance Release can not work in Emulator yet it works on device. This problem had been recorded in the SDK release notes, but there is a solution.

Description

After building the "BrCtlSampleApp" example in S60 SDK 3RD ED. Maintenance Release, the result could be run in the SDK emulator. But the screen shows no content even the page is loaded. This is caused by some bug in BrowserEngine component in the SDK emulator.

How to reproduce

N/A

Solution

Add the following line

```
iBrCtlInterface->ActivateL();
```

after every "`CreateBrowserControlL()`" function call.