

## Archived:Bluetooth SCO data links are not supported (Known Issue)

Archived: This article is **archived** because it is not considered relevant for third-party developers creating commercial solutions today. If you think this article is still relevant, let us know by adding the template {{ReviewForRemovalFromArchive|user=~~~|write your reason here}}.

## Description

SCO (Synchronous Connection Oriented) data links are not supported by the Bluetooth stack in S60 3rd Edition devices.

## Solution

No solution available. 3rd party developers can use ACL data links instead.